

Martin Diesel Service Ltd

237 PTH 52W, Steinbach, MB R5G 2S9

Phone: (204)326-2408 ~ Fax: (204)326-1693

Toll Free 1-888-882-9399

Email:info@martindiesel.net

GST #R103544656

Invoice

Bill To RM of Ste. Anne (EMAIL x2)
Box 6 Grp 50 RR1
395 Traverse Road
Ste. Anne, MB R5H 1R1
Canada

Plate MB CGC486
Description 2005 Sterling
VIN 2FZACHDC95AU93870
Unit Pumper - Richer Fire
Odometer 40,340

Business (204) 422-5929
Chris-Fire Chief +1 (204) 381-0057
Invoices info@rmofsteanne.com

Invoice # 215980
Work Order # 261112
Service Advisor Clint Wiens
Technician Martin Diesel

Invoice Date 1/14/2026 8:04 AM
Appointment 12/23/2025 11:19 AM
Promised 12/23/2025 11:19 AM

Service

Gov't Safety Inspection - Hvy Truck

10-SAFETY DECAL - MANITOBA GOV'T	1 Unit	\$5.00 / Unit	\$5.00 G
Labour: C-Inspection (C026364)			\$250.00 *G
	Sub		\$255.00

Safety repairs

Repairs required to complete safety

Safety repairs: Inspect and measure brake lining. Repair loose right side dash panel, fabricate support brackets, install and secure. Weld to repair small burn holes at tail pipe elbow.			\$720.50 *GP
10-NPNRIVET - RIVET	10 Unit	\$0.80 / Unit	\$8.00 GP
12-NPN O RING - O RING	1 Unit	\$1.18 / Unit	\$1.18 GP
	Sub		\$729.68

Service Air Dryer

Labor: Remove and replace air dryer cartridge and purge valve.			\$196.50 *GP
04-107794BXR - CARTRIDGE,AD9 AIR DRYER	1 Unit	\$57.42 / Unit	\$57.42 GP
04-BAR5004341 - AD9 PURGE VALVE	1 Unit	\$118.92 / Unit	\$118.92 GP
	Sub		\$372.84

COMPLETE SERVICE

CHANGE OIL & FILTERS, LUBE CHASSIS & CHECK ALL FLUID LEVELS.

Labour			\$130.00 *GP
19-LF667 - OIL FILTER (incl EHC of 1.00)	1 Unit	\$18.37 / Unit	\$18.37 GP
19-AF26418 - FILTER,HEATER A/C STERLING	1 Unit	\$31.97 / Unit	\$31.97 GP
19-FS19593 - MERCEDES FUEL FILTER	1 Unit	\$50.62 / Unit	\$50.62 GP
19-FF5324 - FUEL FILTER(EHC .50 INCLUDED)	1 Unit	\$23.45 / Unit	\$23.45 GP
19-AF4878 - AIR FILTER	1 Unit	\$51.15 / Unit	\$51.15 GP
21-DMO - 15W40 ENGINE OIL	22 Unit	\$6.43 / Unit	\$141.46 GP
	Sub		\$447.02

RE-TORQUE WHEELS AND U-BOLTS WITHIN 100KM. THIS IS CUSTOMER'S RESPONSIBILITY.

Modifications to emissions or horsepower may void warranties.

Return/Refund Policy: Please provide this invoice number when returning any product for a refund request. Returns will be accepted up to 30 days from invoice date in their original packaging and please note that all returned items are subject to a restocking fee. Special order and electrical parts may not be acceptable for return due to original manufacturers guidelines.

Battery connection service

Clean all battery cables & posts

Labor: Clean battery connections. Load test batteries and found three batteries weak. Remove and replace three batteries.

08-31-ECL(HP31DW) - BATTERY, STUD TOP.700CCA	3 Unit	\$179.70 / Unit	\$539.10 GP
		Sub	\$670.10

Total Parts		\$1,046.64
Total Labor		<u>\$1,428.00</u>
Total Before Taxes & Miscellaneous Charges		\$2,474.64

(*) Shop Supplies		\$92.82 GP
(G) Canadian Goods and Services Tax (GST)	5 %	\$128.37
(P) Manitoba Provincial Sales Tax (PST)	7 %	\$161.87
Grand Total		\$2,857.70

RM of Ste. Anne (EMAIL x2) charged \$2,857.70 to Account - RM of Ste. Anne (EMAIL x2) - Net 30 Days

I acknowledge my indebtedness to Martin Diesel Service Ltd for the amount of \$ _____, for the work listed above, which has been completed on my authorization.

I further acknowledge that Martin Diesel Service intends to rely on the rights of a lienholder under the Garage Keepers Act.

Signature: _____

Name: _____

RE-TORQUE WHEELS AND U-BOLTS WITHIN 100KM. THIS IS CUSTOMER'S RESPONSIBILITY.

Modifications to emissions or horsepower may void warranties.

Return/Refund Policy: Please provide this invoice number when returning any product for a refund request. Returns will be accepted up to 30 days from invoice date in their original packaging and please note that all returned items are subject to a restocking fee. Special order and electrical parts may not be acceptable for return due to original manufacturers guidelines.